

Stonedon Yard – Site Map & Traffic Flow

Truck entry, weighbridge, waiting bays, material drop-off points and exit route

CLEANER
SAFER
SMARTER



1

WEIGH IN

Enter the yard via Stonedon Drive and report to the weighbridge (located at the far right) to weigh in.

2

DROP SAMPLE

After weighing in, drop a sample at the Sample Shed (located on the right), before proceeding to the waiting bays.

3

WAITING LINES

Join one of the 3 dedicated waiting lines (4.5m wide each) and wait for your turn.

4

DUMPING PIT (WATER)

ONLY ACCEPTS:

- Hydro
- Drilling mud – Bentonite

5

RESOURCE RECOVERY PLANT

ONLY ACCEPTS:

- Hydro
- Catchpit waste
- Road sweepings

6

TREATMENT SHED

ONLY ACCEPTS:

- Grease trap
- Interceptor waste
- Hydrocarbons
- Bulk chemicals

Please wait for operator to provide instructions before entry.

7

WEIGH OUT & EXIT

After tipping and disposal of waste, return to the weighbridge (same location as step 1) to weigh out, then follow the blue arrows and exit right

Legend



Go here first (to dump/dispose of waste)



After tipping and disposal of waste, go to exit

Key Information

- 3 waiting bays (4.5m wide each – 3 trucks can hold)
- Dumping Pit – 10m long x 3m wide (two trucks can dump)
- Resource Recovery Plant – one truck can dump
- Follow yellow arrows first, then blue arrows to exit.



INTERGROUP

CLEANER SAFER SMARTER

